

VanBoxmeer & Stranges Ltd.

458 Queens Ave
London, Ontario
N6B 1X9
P: (519) 433-4661
vbands@vbands.com

4802 Portage Rd, Unit 1
Niagara Falls, Ontario
L2A 6E3
P: (905) 357-2030
al@vbands.com

July 5, 2019
VB&S #: 19158

JAM Properties
180 Cheapside Street
London, Ontario
N6A 1Z8
Attn: Mr. Archie Leach

JAM Properties
Structural Review and Comments
123 Queens Avenue
London, Ontario
SUPPLEMENTAL REPORT #1

Dear Mr. Leach:

This letter serves to supplement our report dated May 07, 2019. VB&S was provided the opportunity to add to the original report and determine the structural integrity of the structure and to test the concrete and determine whether the concrete is sound. The assessment of the building was completed in two ways. First, by constructing a digital model of the building and completing a structural analysis. Second, by taking core samples of the existing concrete and testing them to determine the structural integrity of the concrete.

1.1 Structural Analysis

On May 14, 2019, Rick Stranges, P. Eng., and Michael Hatt, EIT, (of VB&S) were on site to survey the concrete structure. Physical measurements of the entire structure were taken. The measurements included but were not limited to the wall thickness, floor thickness, floor beam dimensions/locations and the reinforcing steel size and spacing (where exposed) in the walls and piers.

VB&S used these measurements to construct a virtual 3D model using E-Tabs software. E-Tabs is an integrated structural analysis and design software that allows structural engineers to analyze and design various structures. Results from the software allow the engineer to determine which virtual elements are overstressed, and to revise specific parameters until that element is capable of supporting the applied loads.

When the virtual model was built, loads were applied to the structure. The loads as prescribed by the Ontario Building Code include the self-weight of the concrete, dead and live loads applied to the floor structure, and wind loads. Given the age of the building, it was not required to check that the structure would be capable of resisting any seismic load. In discussions with the City, we agreed that as the structure and the occupancy was not changing at this time, and as the original building was not designed for seismic loads, this

study would not have to meet that requirement.

Once the E-tabs results were obtained, VB&S used a software called “S-Concrete” to check the capacity of the elements that were shown to be overstressed in E-Tabs. We use S-Concrete software to design structural concrete elements and in this case walls. The program allows us to construct a virtual wall and precisely arrange the reinforcing within that wall. In this way, S-Concrete allows for a more accurate analysis of specific structural elements. After obtaining the loads and reactions of the overstressed elements from the E-Tabs model, we applied those loads to the wall in S-Concrete. We were then able to verify the stresses in the wall and determine if the maximum permissible stresses in the wall have been exceeded.

1.2 Concrete Sampling (PML)

Peto MacCallum Ltd. (PML) was requested by VB&S to obtain samples of the concrete structure and report on the integrity of the concrete. On June 13, 2019, two PML technicians met with Michael Hatt on site. PML attempted to take concrete samples at three slab locations and one wall location on the third floor of the building. See Appendix ‘B’ Figure 3.

PML reported that the concrete was in such poor condition that proper samples could not be cored and sent to the lab for analysis. Due to the severe deterioration and delamination of the concrete, PML abandoned taking additional samples from the remaining floors. It was reported that attempting to obtain additional samples would be useless as the crumbled and broken concrete could not be tested. Photographs #2 and #4 of the PML report show the condition of the delaminated concrete, where asphalt topping was removed. It was verified by both VB&S and PML that the concrete was severely deteriorated and spalled.

PML notes that the concrete is in very poor condition, and as a result the concrete has extremely low compressive strength. They note that the concrete is in such a state that the slabs are not suitable for the purpose for which they were originally designed.

The condition of the corroded reinforcing and the severely deteriorated concrete renders the floor beyond repair.

1.3 Structural Results

The entire structure was modelled and analyzed, and some of the areas that are overstressed are highlighted in this report. It was determined that most of the walls along the east and south ends of the building were severely overstressed under the OBC applied wind and gravity loads. As shown in the analysis results (Appendix ‘C’), walls in locations noted **V**, **W**, **X**, **Y** and **Z**, as shown in Appendix ‘B’, are overstressed by as much as twice their capacity. Below is a summary of the results in the 5 wall locations highlighted in this report.

<u>Wall Location 'V'</u>	E-Tabs Model	– Overstressed
	S-Concrete Analysis	– 142% Overstressed
	S-Concrete Warnings	– Warnings of Inadequate Steel
<u>Wall Location 'W'</u>	E-Tabs Model	– Overstressed
	S-Concrete Analysis	– 23% Overstressed
	S-Concrete Warnings	– Warnings of Inadequate Steel
<u>Wall Location 'X'</u>	S-Concrete Model	– Overstressed
	S-Concrete Analysis	– 8% Overstressed
	S-Concrete Warnings	– Warnings of Inadequate Steel
<u>Wall Location 'Y'</u>	S-Concrete Model	– Overstressed
	S-Concrete Analysis	– 102% Overstressed
	S-Concrete Warnings	– Warnings of Inadequate Steel
<u>Wall Location 'Z'</u>	S-Concrete Model	– Overstressed
	S-Concrete Analysis	– 48% Overstressed
	S-Concrete Warnings	– Warnings of Inadequate Steel

It is also important to consider that the digital analysis of the structure assumes the concrete and reinforcing steel to be working in tandem as designed. However, based on inspection by VB&S and PML, the concrete has been severely cracked and delaminated in many locations, weakening its bond with the reinforcing steel. With this in mind, the structural elements of the building cannot be expected to perform even to the level assumed by the digital analysis. This leaves the structural elements even more overstressed than shown above.

In the Peto MacCallum Ltd. (PML) report, it was noted that the concrete strength could not be determined. A structural analysis of the floor slabs was not completed, as without the concrete strength a calculated concrete stress could not be determined.

2.1 Summary

The analysis results revealed that many of the walls were highly overstressed. The level of overstress removes all factors of safety from the wall, leaving the wall in a severe state of lateral instability.

The inability of PML to obtain a concrete sample from the concrete floor is a major concern. PML notes that the concrete is so deteriorated that it crumbled when trying to extract a core, and therefore the concrete strength could not be determined.

The results of the virtual model/analysis, and the concrete sampling obtained from PML, confirm the assumptions we noted in our original report.

It is our professional opinion that this building is structurally unsound. We recommend that this structure be demolished immediately as it is unsafe.

We thank you for the opportunity to submit this report. If you have any questions, please do not hesitate to call.

Regards,
**VanBoxmeer & Stranges
Engineering Ltd.**



Rick Stranges, P. Eng.
Vice-President
RAS/ras



APPENDIX 'A'

Peto MacCallum Ltd. - Report

June 13, 2019

PML Ref.: 19LM005

Report: 1

Ms. Martha Leach
JAM Properties
180 Cheapside Street
London, Ontario
N6A 1Z8

Dear Ms. Leach

Concrete Coring and Testing
123 Queens Avenue
London, Ontario

Peto MacCallum Ltd. (PML) visited the referenced project site on June 13, 2019, at the request of Mr. Michael Hatt of VanBoxmeer & Strangers Engineering Limited, to extract a number of concrete core samples to be submitted to PML's laboratory for compressive strength testing, to assist in the analysis on the structural integrity of the noted concrete building.

Upon arrival at the site, located at 123 Queens Ave, London, Ontario, it was observed that the building is an old concrete building with obvious signs of severe cracking in the walls and the suspended floor slab area. Inspection of the suspended floor slab, at some areas, indicated that a thin layer of asphalt with approximate thickness of 25 mm was overlying the concrete floor slab where rebar was observed at approximately 150 mm from top of the slab. Upon trying to core-drill, the concrete crumble and broke into pieces.

Based on our observations during the attempt to extract core samples for testing, the slab concrete has deteriorated to the extent that sound (or intact) concrete core samples could not be extracted. The fact that the concrete easily crumbled into pieces upon core-drilling is indicative of deteriorated concrete with extremely low compressive strength. From a concrete material view point, the concrete slab is not suitable for the purpose for which the structure was designed. A structural analysis/evaluation should be carried out to assess the remaining service life, if any.

As a result and based on our discussions with Mr. Hatt who was present at the site during our visit, no concrete coring was performed at the noted concrete building.

Photographs showing the observed poor concrete condition in the building are attached for reference.

Should you have any questions regarding the information presented, please contact our office.

Sincerely

Peto MacCallum Ltd



Souzan Dabbagh, M.Eng, P.Eng.
Discipline Manager – Inspection and Testing
and Geotechnical Services

SD:ak

Enclosure(s) : 4

1 cc: JAM Properties (email only)

1 cc: Van Boxmeer & Strangers Engineering Limited (email only)

4023 Meadowbrook Drive, Unit 103, London, Ontario N6L 1E6

Tel: (519) 203-7500

E-mail: kitchener@petomacallum.com

BARRIE, COLLINGWOOD, HAMILTON, KITCHENER, LONDON, TORONTO



APPENDIX A
Site Photographs



Photograph No. 1 – Severe Concrete Floor and Wall Cracks



Photograph No. 2 – Asphalt Layer Overlying the Poor Concrete Floor Slab



Photograph No. 3 – Overall Picture Showing Poor Concrete Floor and Wall Conditions



Photograph No. 4 – Broken Pieces/Crumble of Concrete Floor Showing Unsuitable Coring Conditions

APPENDIX 'B'

Analysis Model




Figure 1 - 3D Model




Figure 2 - Roof Framing Plan




Figure 3 - 3rd Floor Framing Plan




Figure 4 - Gridline 1 Elevation




Figure 5 - Gridline 5 Elevation




Figure 6 - Gridline H Elevation

APPENDIX 'C'

Analysis Results

ETABS Shear Wall Design

CSA A23.3-14 Pier Design

Pier Details

Story ID	Pier ID	Centroid X (mm)	Centroid Y (mm)	Length (mm)	Thickness (mm)	LLRF
ROOF	PW21	5104.5	0	5641	203.2	1

Material Properties

E_c (MPa)	f'_c (MPa)	Lt.Wt Factor (Unitless)	f_y (MPa)	f_{yk} (MPa)
24942	25	1	275	275

Design Code Parameters

Φ_c	Φ_s	IP_{MAX}	IP_{MIN}	P_{MAX}
0.65	0.85	0.04	0.0025	0.8

Pier Leg Location, Length and Thickness

Station Location	ID	Left X_1 (mm)	Left Y_1 (mm)	Right X_2 (mm)	Right Y_2 (mm)	Length (mm)	Thickness (mm)
Top	Leg 1	2284	0	7925	0	5641	203.2
Bottom	Leg 1	2284	0	7925	0	5641	203.2

Flexural Design for P_f , M_{f1} and M_{f2}

Station	D/C	Flexural	P_f (kN)	M_{f1} (kN-m)	M_{f2} (kN-m)
Top	1.026	4. 1.25D + 1.4W(y) + 0.5L	82.0934	38.3381	49.0831
Bottom	0.238	4. 1.25D + 1.4W(y) + 0.5L	208.1524	-23.5646	-110.4123

Design Inadequacy Message: Pier fails in flexure or P-M-M interaction !!

Shear Design

Station Location	ID	Rebar (mm ² /m)	Shear Combo	P_f (kN)	M_f (kN-m)	V_f (kN)	V_c (kN)	V_r (kN)
Top	Leg 1	0	12. 1.25D - 1.4W(y) + 0.5L	93.4772	81.0846	57.4569	0	0
Bottom	Leg 1	0	12. 1.25D - 1.4W(y) + 0.5L	219.5361	133.4678	57.4569	0	0

Boundary Element Check (Part 1 of 2)

Station Location	ID	Edge Length (mm)	Governing Combo	P_f (kN)	M_f (kN-m)	c (mm)	Inelastic Rotational Demand
Top	Leg 1	0	14. D - Q(y) + 0.5L	74.2114	60.5332	0	0
Bottom	Leg 1	0	14. D - Q(y) + 0.5L	0	0	0	0

Boundary Element Check (Part 2 of 2)

Inelastic Rotational Capacity	Ductility Status
0	Not Needed
0	Not Needed

LOCATION V: ETABS Results for Wall on Gridline 1 From B to C

S-CONCRETE 2019.1.1 (c) S-FRAME Software Inc. www.s-frame.com			
File Name: Q:\... Analysis\19158 SCONC\19158 Wall Test.SCO		Summary	
Section Name		Status	Unacceptable
Concrete Section		Maximum	1.000
Consultant		V (shear) Util	0.108
VB&S		N vs M Util	2.421
Canadian Building Standards			
CSA Standard A23.3-14, "Design of Concrete Structures"			
CSA Standard A23.1-04, "Concrete Materials and Methods of Concrete Construction"			
Design Aids, Manuals, and Handbooks			
"Concrete Design Handbook", Cement Association of Canada, 3rd Edition, 2006			
"Prestressed Concrete Structures", Collins and Mitchell, Prentice Hall Inc., 1991 (MCFT)			
Section Dimensions			
I-Shape	Material Properties		
L1 = 5610 mm	Gross Properties		
T1 = 200 mm	Effective Properties		
	Overstrength Factors		
	Quantities (approx.)		
	Panel 1		
	N vs M Results		
	Axial Utilization		
	Moment Utilization		
	Shear and Torsion Utilization		
	Shear Z-Direction		
	Shear Y-Direction		

LOCATION V: S-Concrete Results for Wall on Gridline 1 From B to C – Page 1

Ductility Requirements		
No Earthquake Loads		
List of Messages		
Message 1	Unacceptable	Axial Load and Moment Utilization equals or exceeds Maximum. Clauses 10.1, 10.10, or 14.2.2 of A23.3
Message 17	Warning	f_y of Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 18	Warning	f_y of Shear Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 47	Warning	Panel Vertical Steel Ratio does not meet the minimum. Clause 14.1.8.5 of A23.3
Message 49	Warning	Panel Horizontal Steel Ratio does not meet the minimum. Clause 14.1.8.6 of A23.3
Message 68	Warning	Zone required with minimum bars. Clause 14.1.8.8.1 or 21.6.3.7.4 of A23.3
Message 75	Warning	Horizontal bars may require sideways hooks or may need to be anchored within zone Clause 21.5.5.3 of A23.3

LOCATION V: S-Concrete Results for Wall on Gridline 1 From B to C – Page 2

ETABS Shear Wall Design

CSA A23.3-14 Pier Design

Pier Details

Story ID	Pier ID	Centroid X (mm)	Centroid Y (mm)	Length (mm)	Thickness (mm)	LLRF
ROOF	PW1	3982.5	9093	7925	203.2	1

Material Properties

E_c (MPa)	f'_c (MPa)	Lt.Wt Factor (Unitless)	f_y (MPa)	f_{yk} (MPa)
24942	25	1	275	275

Design Code Parameters

Φ_c	Φ_s	IP_{MAX}	IP_{MIN}	P_{MAX}
0.65	0.85	0.04	0.0025	0.8

Pier Leg Location, Length and Thickness

Station Location	ID	Left X_1 mm	Left Y_1 mm	Right X_2 mm	Right Y_2 mm	Length mm	Thickness mm
Top	Leg 1	0	9093	7925	9093	7925	203.2
Bottom	Leg 1	0	9093	7925	9093	7925	203.2

Flexural Design for P_f , M_{f2} and M_{f3}

Station	D/C	Flexural	P_f kN	M_{f2} kN-m	M_{f3} kN-m
Top	1.036	$3.125D + 1.4W(x) + 0.5L$	105.5626	-53.196	-123.9426
Bottom	0.049	$12.125D - 1.4W(y) + 0.5L$	289.9453	19.5598	90.5061

Design Inadequacy Message: Pier fails in flexure or P-M-M interaction !!

Shear Design

Station Location	ID	Rebar mm^2/m	Shear Combo	P_f kN	M_f kN-m	V_f kN	V_c kN	V_r kN
Top	Leg 1	0	$3.125D + 1.4W(x) + 0.5L$	105.5626	123.9426	49.1424	0	0
Bottom	Leg 1	0	$3.125D + 1.4W(x) + 0.5L$	289.9453	93.1941	41.1722	0	0

Boundary Element Check (Part 1 of 2)

Station Location	ID	Edge Length (mm)	Governing Combo	P_f kN	M_f kN-m	c mm	Inelastic Rotational Demand
Top	Leg 1	0	$14.D - Q(y) + 0.5L$	85.7966	-92.6012	0	0
Bottom	Leg 1	0	$14.D - Q(y) + 0.5L$	0	0	0	0

Boundary Element Check (Part 2 of 2)

Inelastic Rotational Capacity	Ductility Status
0	Not Needed
0	Not Needed

LOCATION W: ETABS Results for Wall on Gridline 5 From A to C

S-CONCRETE 2019.1.1 (c) S-FRAME Software Inc. www.s-frame.com			
File Name: Q:\...alysis\19158 SCONC\19158 Wall Test 4.SCO		Summary	
Section Name		Status	
Concrete Section	VB&S	Unacceptable	
		Maximum	1.000
		V (shear) Util	0.112
		N vs M Util	1.227
Canadian Building Standards			
CSA Standard A23.3-14, "Design of Concrete Structures"			
CSA Standard A23.1-04, "Concrete Materials and Methods of Concrete Construction"			
Design Aids, Manuals, and Handbooks			
"Concrete Design Handbook", Cement Association of Canada, 3rd Edition, 2006			
"Prestressed Concrete Structures", Collins and Mitchell, Prentice Hall Inc., 1991 (MCFT)			
Section Dimensions	Material Properties	Gross Properties	Effective Properties
I-Shape	fc' = 25 MPa	Zbar = 0 mm	Ae = 1585.0xE3 mm ²
L1 = 7825 mm	fy (panel vert) = 275.0 MPa	Ybar = 0 mm	Ie (y-y) = 5283.3xE6 mm ⁴
T1 = 200 mm	fy (panel horz) = 275.0 MPa	Ag = 1585.0xE3 mm ²	Ie (z-z) = 8295.6xE9 mm ⁴
	fy (zone vert) = 275.0 MPa	Ig (y-y) = 5283.3xE6 mm ⁴	Ase (Y) = 1320.8xE3 mm ²
	fy (zone horz) = 275.0 MPa	Ig (z-z) = 8295.6xE9 mm ⁴	Ase (Z) = 1320.8xE3 mm ²
	Wc = 2400 kg/m ³	Ashear (Y) = 1320.8xE3 mm ²	Je = 20797xE6 mm ⁴
	Ws = 7850 kg/m ³	Ashear (Z) = 1320.8xE3 mm ²	
	Poisson's Ratio = 0.2	Jg = 20797xE6 mm ⁴	Overstrength Factors
Quantities (approx.)	hagg = 20 mm		Normal (y-y) = 1.5
Concrete = 3799 kg/m	Es = 200000 MPa		Normal (z-z) = 1.5
Steel = 28.6 kg/m	Ec = 24943 MPa		Rd = 1.5, Ro = 1.3
Primary = 14.9 kg/m	Gc = 10393 MPa		
Secondary = 13.7 kg/m	fr = 3.0 MPa		
Panel 1			
19-10M @ 450 Vert			
10M @ 450 Horz			
N vs M Results		Axial Utilization	Moment Utilization
GLC	61	Nf = -133.8 kN	Mf = 136.3 kNm
Status	Unacceptable	Nr (max) = -11740.3 kN	Mr = 111.1 kNm
Utilization	1.227	Utilization = 0.011	Utilization = 1.227
Maximum	1.000		
Theta	300°		
w	1.00		
Shear and Torsion Utilization		Shear Z-Direction	Shear Y-Direction
GLC	157	Nf = -105.3 kN	Nf = -105.3 kN
Status	Acceptable	Mf (y-y) = -53.7 kNm	Mf (z-z) = -120.2 kNm
Utilization	0.112	Vfz = 47.9 kN	Vfy = 16.6 kN
Maximum	1.000	bw = 7825 mm	bw = 200 mm
Method	Simplified	d = 100 mm	d = 6340 mm

LOCATION W: S-Concrete Results for Wall on Gridline 5 From A to C – Page 1

<u>Ductility Requirements</u>		
No Earthquake Loads		
<u>List of Messages</u>		
Message 1	Unacceptable	Axial Load and Moment Utilization equals or exceeds Maximum. Clauses 10.1, 10.10, or 14.2.2 of A23.3
Message 17	Warning	f_y of Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 18	Warning	f_y of Shear Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 47	Warning	Panel Vertical Steel Ratio does not meet the minimum. Clause 14.1.8.5 of A23.3
Message 49	Warning	Panel Horizontal Steel Ratio does not meet the minimum. Clause 14.1.8.6 of A23.3
Message 68	Warning	Zone required with minimum bars. Clause 14.1.8.8.1 or 21.6.3.7.4 of A23.3
Message 75	Warning	Horizontal bars may require sideways hooks or may need to be anchored within zone Clause 21.5.5.3 of A23.3
Message 85	Warning	Simplified Method of Shear Design cannot be used for this section. Clauses 11.3.6.3 or 11.3.6.1 of A23.3

LOCATION W: S-Concrete Results for Wall on Gridline 5 From A to C – Page 2

S-CONCRETE 2019.1.1 (c) S-FRAME Software Inc. www.s-frame.com			
File Name: Q:\... alysis\19158 SCONC\19158 Wall Test 2.SCO		Summary	
Section Name		Status	
Concrete Section	VB&S	Unacceptable	
		Maximum 1.000	
		V (shear) Util 0.158	
		N vs M Util 1.084	
Canadian Building Standards			
CSA Standard A23.3-14, "Design of Concrete Structures"			
CSA Standard A23.1-04, "Concrete Materials and Methods of Concrete Construction"			
Design Aids, Manuals, and Handbooks			
"Concrete Design Handbook", Cement Association of Canada, 3rd Edition, 2006			
"Prestressed Concrete Structures", Collins and Mitchell, Prentice Hall Inc., 1991 (MCFT)			
Section Dimensions	Material Properties	Gross Properties	Effective Properties
I-Shape	fc' = 25 MPa	Zbar = 0 mm	Ae = 354000 mm ²
L1 = 1770 mm	fy (panel vert) = 275.0 MPa	Ybar = 0 mm	Ie (y-y) = 1180.0xE6 mm ⁴
T1 = 200 mm	fy (panel horz) = 275.0 MPa	Ag = 354000 mm ²	Ie (z-z) = 92421xE6 mm ⁴
	fy (zone vert) = 275.0 MPa	Ig (y-y) = 1180.0xE6 mm ⁴	Ase (Y) = 295000 mm ²
	fy (zone horz) = 275.0 MPa	Ig (z-z) = 92421xE6 mm ⁴	Ase (Z) = 295000 mm ²
	Wc = 2400 kg/m ³	Ashear (Y) = 295000 mm ²	Je = 4383.9xE6 mm ⁴
	Ws = 7850 kg/m ³	Ashear (Z) = 295000 mm ²	
	Poisson's Ratio = 0.2	Jg = 4383.9xE6 mm ⁴	Overstrength Factors
Quantities (approx.)	hagg = 20 mm		Normal (y-y) = 1.5
Concrete = 848 kg/m	Es = 200000 MPa		Normal (z-z) = 1.5
Steel = 6.9 kg/m	Ec = 24943 MPa		Rd = 1.5, Ro = 1.3
Primary = 3.9 kg/m	Gc = 10393 MPa		
Secondary = 2.9 kg/m	fr = 3.0 MPa		
Panel 1			
5-10M @ 450 Vert			
10M @ 450 Horz			
N vs M Results		Axial Utilization	Moment Utilization
GLC	559	Nf = -0.6 kN	Mf = 12.4 kNm
Status	Unacceptable	Nr (max) = -2631.3 kN	Mr = 11.5 kNm
Utilization	1.084	Utilization = 0.000	Utilization = 1.084
Maximum	1.000		
Theta	180°		
w	1.00		
Shear and Torsion Utilization		Shear Z-Direction	Shear Y-Direction
GLC	230	Nf = -102.3 kN	Nf = -102.3 kN
Status	Acceptable	Mf (y-y) = -10.5 kNm	Mf (z-z) = 34.5 kNm
Utilization	0.158 = Uz + Uy	Vfz = 7.5 kN	Vfy = 24.2 kN
Maximum	1.000	bw = 1770 mm	bw = 200 mm
Method	Simplified	d = 100 mm	d = 1416 mm

LOCATION X: S-Concrete Results for Wall on Gridline 5 From D to E – Page 1

<u>Ductility Requirements</u>		
No Earthquake Loads		
<u>List of Messages</u>		
Message 1	Unacceptable	Axial Load and Moment Utilization equals or exceeds Maximum. Clauses 10.1, 10.10, or 14.2.2 of A23.3
Message 17	Warning	fy of Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 18	Warning	fy of Shear Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 47	Warning	Panel Vertical Steel Ratio does not meet the minimum. Clause 14.1.8.5 of A23.3
Message 49	Warning	Panel Horizontal Steel Ratio does not meet the minimum. Clause 14.1.8.6 of A23.3
Message 68	Warning	Zone required with minimum bars. Clause 14.1.8.8.1 or 21.6.3.7.4 of A23.3
Message 75	Warning	Horizontal bars may require sideways hooks or may need to be anchored within zone Clause 21.5.5.3 of A23.3
Message 85	Warning	Simplified Method of Shear Design cannot be used for this section. Clauses 11.3.6.3 or 11.3.6.1 of A23.3

LOCATION X: S-Concrete Results for Wall on Gridline 5 From D to E – Page 2

S-CONCRETE 2019.1.1 (c) S-FRAME Software Inc. www.s-frame.com			
File Name: Q:\... alysis\19158 SCONC\19158 Wall Test 3.SCO		Summary	
Section Name Concrete Section		Status Unacceptable	
Consultant VB&S		Maximum 1.000	
		V (shear) Util 0.226	
		N vs M Util 2.017	
Canadian Building Standards			
CSA Standard A23.3-14, "Design of Concrete Structures"			
CSA Standard A23.1-04, "Concrete Materials and Methods of Concrete Construction"			
Design Aids, Manuals, and Handbooks			
"Concrete Design Handbook", Cement Association of Canada, 3rd Edition, 2006			
"Prestressed Concrete Structures", Collins and Mitchell, Prentice Hall Inc., 1991 (MCFT)			
Section Dimensions	Material Properties	Gross Properties	Effective Properties
I-Shape	fc' = 25 MPa	Zbar = 0 mm	Ae = 220000 mm ²
L1 = 1100 mm	fy (panel vert) = 275.0 MPa	Ybar = 0 mm	Ie (y-y) = 733333xE3 mm ⁴
T1 = 200 mm	fy (panel horz) = 275.0 MPa	Ag = 220000 mm ²	Ie (z-z) = 22183xE6 mm ⁴
	fy (zone vert) = 275.0 MPa	Ig (y-y) = 733333xE3 mm ⁴	Ase (Y) = 183333 mm ²
	fy (zone horz) = 275.0 MPa	Ig (z-z) = 22183xE6 mm ⁴	Ase (Z) = 183333 mm ²
	Wc = 2400 kg/m ³	Ashear (Y) = 183333 mm ²	Je = 2597.2xE6 mm ⁴
	Ws = 7850 kg/m ³	Ashear (Z) = 183333 mm ²	
	Poisson's Ratio = 0.2	Jg = 2597.2xE6 mm ⁴	Overstrength Factors
	hagg = 20 mm		Normal (y-y) = 1.5
Quantities (approx.)	Es = 200000 MPa		Normal (z-z) = 1.5
Concrete = 527 kg/m	Ec = 24943 MPa		Rd = 1.5, Ro = 1.3
Steel = 4.9 kg/m	Gc = 10393 MPa		
Primary = 3.1 kg/m	fr = 3.0 MPa		
Secondary = 1.8 kg/m			
Panel 1			
4-10M @ 450 Vert			
10M @ 450 Horz			
N vs M Results		Axial Utilization	Moment Utilization
GLC	55	Nf = -18.6 kN	Mf = 22.3 kNm
Status	Unacceptable	Nr (max) = -1646.1 kN	Mr = 11.0 kNm
Utilization	2.017	Utilization = 0.011	Utilization = 2.017
Maximum	1.000		
Theta	165°		
w	1.00		
Shear and Torsion Utilization		Shear Z-Direction	Shear Y-Direction
GLC	136	Nf = -29.9 kN	Nf = -29.9 kN
Status	Acceptable	Mf (y-y) = -13.4 kNm	Mf (z-z) = -13.4 kNm
Utilization	0.226	Vfz = 12.6 kN	Vfy = 6.8 kN
Maximum	1.000	bw = 1100 mm	bw = 200 mm
Method	Simplified	d = 100 mm	d = 880 mm

LOCATION Y: S-Concrete Results for Wall on Gridline 5 From F1 to F2 – Page 1

<u>Ductility Requirements</u>		
No Earthquake Loads		
<u>List of Messages</u>		
Message 1	Unacceptable	Axial Load and Moment Utilization equals or exceeds Maximum. Clauses 10.1, 10.10, or 14.2.2 of A23.3
Message 17	Warning	fy of Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 18	Warning	fy of Shear Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 47	Warning	Panel Vertical Steel Ratio does not meet the minimum. Clause 14.1.8.5 of A23.3
Message 49	Warning	Panel Horizontal Steel Ratio does not meet the minimum. Clause 14.1.8.6 of A23.3
Message 68	Warning	Zone required with minimum bars. Clause 14.1.8.8.1 or 21.6.3.7.4 of A23.3
Message 75	Warning	Horizontal bars may require sideways hooks or may need to be anchored within zone Clause 21.5.5.3 of A23.3
Message 85	Warning	Simplified Method of Shear Design cannot be used for this section. Clauses 11.3.6.3 or 11.3.6.1 of A23.3

LOCATION Y: S-Concrete Results for Wall on Gridline 5 From F1 to F2 – Page 2

S-CONCRETE 2019.1.1 (c) S-FRAME Software Inc. www.s-frame.com			
File Name: Q:\... 8 Wall Test 5 Gridline H From 1 to 2.SCO		Summary	
Section Name Concrete Section		Consultant VB&S	
		Status	Unacceptable
		Maximum	1.000
		V (shear) Util	0.446
		N vs M Util	1.478
Canadian Building Standards			
CSA Standard A23.3-14, "Design of Concrete Structures"			
CSA Standard A23.1-04, "Concrete Materials and Methods of Concrete Construction"			
Design Aids, Manuals, and Handbooks			
"Concrete Design Handbook", Cement Association of Canada, 3rd Edition, 2006			
"Prestressed Concrete Structures", Collins and Mitchell, Prentice Hall Inc., 1991 (MCFT)			
Section Dimensions	Material Properties	Gross Properties	Effective Properties
I-Shape	fc' = 25 MPa	Zbar = 0 mm	Ae = 330000 mm ²
L1 = 1650 mm	fy (panel vert) = 275.0 MPa	Ybar = 0 mm	Ie (y-y) = 1100.0xE6 mm ⁴
T1 = 200 mm	fy (panel horz) = 275.0 MPa	Ag = 330000 mm ²	Ie (z-z) = 74869xE6 mm ⁴
	fy (zone vert) = 275.0 MPa	Ig (y-y) = 1100.0xE6 mm ⁴	Ase (Y) = 275000 mm ²
	fy (zone horz) = 275.0 MPa	Ig (z-z) = 74869xE6 mm ⁴	Ase (Z) = 275000 mm ²
	Wc = 2400 kg/m ³	Ashear (Y) = 275000 mm ²	Je = 4063.9xE6 mm ⁴
	Ws = 7850 kg/m ³	Ashear (Z) = 275000 mm ²	
	Poisson's Ratio = 0.2	Jg = 4063.9xE6 mm ⁴	Overstrength Factors
	hagg = 20 mm		Normal (y-y) = 1.5
Quantities (approx.)	Es = 200000 MPa		Normal (z-z) = 1.5
Concrete = 791 kg/m	Ec = 24943 MPa		Rd = 1.5, Ro = 1.3
Steel = 6.6 kg/m	Gc = 10393 MPa		
Primary = 3.9 kg/m	fr = 3.0 MPa		
Secondary = 2.7 kg/m			
Panel 1			
5-10M @ 450 Vert			
10M @ 450 Horz			
N vs M Results		Axial Utilization	Moment Utilization
GLC	28	Nf = -32.8 kN	Mf = 22.3 kNm
Status	Unacceptable	Nr (max) = -2457.0 kN	Mn = 17.4 kNm
Utilization	1.478	Utilization = 0.013	Mr = 15.1 kNm
Maximum	1.000		Mp = 20.8 kNm
Theta	199°		
w	1.00		
Shear and Torsion Utilization		Shear Z-Direction	Shear Y-Direction
GLC	137	Nf = -26.5 kN	Nf = -26.5 kN
Status	Acceptable	Mf (y-y) = -3.1 kNm	Mf (z-z) = 17.2 kNm
Utilization	0.446	Vfz = 25.0 kN	Vfy = 50.5 kN
Maximum	1.000	bw = 1650 mm	bw = 200 mm
Method	Simplified	d = 100 mm	d = 1320 mm

LOCATION Z: S-Concrete Results for Wall on Gridline H From 1 to 2 – Page 1

Ductility Requirements		
No Earthquake Loads		
List of Messages		
Message 1	Unacceptable	Axial Load and Moment Utilization equals or exceeds Maximum. Clauses 10.1, 10.10, or 14.2.2 of A23.3
Message 17	Warning	fy of Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 18	Warning	fy of Shear Reinforcing is not within an Acceptable range. Clause 8.5.1 of A23.3, $300 \leq f_y \leq 500$ MPa
Message 47	Warning	Panel Vertical Steel Ratio does not meet the minimum. Clause 14.1.8.5 of A23.3
Message 49	Warning	Panel Horizontal Steel Ratio does not meet the minimum. Clause 14.1.8.6 of A23.3
Message 68	Warning	Zone required with minimum bars. Clause 14.1.8.8.1 or 21.6.3.7.4 of A23.3
Message 75	Warning	Horizontal bars may require sideways hooks or may need to be anchored within zone Clause 21.5.5.3 of A23.3
Message 85	Warning	Simplified Method of Shear Design cannot be used for this section. Clauses 11.3.6.3 or 11.3.6.1 of A23.3

LOCATION Z: S-Concrete Results for Wall on Gridline H From 1 to 2 – Page 2