

CPP Watermain Break

2012 Mt. Carmel, May 23

Damage to Field



Emerg. Command Center



Break uncovered....



Starting pipe removal- 12hrs after reported break



Spent part of the day shutting down the section, pumping off the field, and building a temporary access road to limit the damage to crops.

Broken pre-stressed wires and 1200mm diameter watermain



Removing pipe section




Electromagnetic inspection inside of pipe to ensure no pipes in close proximity of broken section were in distress



Repair almost complete...



Springbank Reservoir at 4:00pm Friday – SCADA Plot



Blue and red squiggly lines are “in-flow” and “out-flow” respectively. No blue (inflow) from 7:00am Wednesday to 9:00pm Thursday.

Green and blue lines are reservoir levels. Bottom of graph is approx. bottom of reservoir.