

**1349 Western Road, London**

**Focused Environmental Impact Study**

**Received from consultants April 13, 2022**

**Reviewed for EEPAC by S. Levin and B. Samuels**

Appreciate the 30 m buffer

Please clarify when the two year warranty period ends and when the monitoring begins

Encourage further removal of buckthorn along north side of Burnlea Way to reduce the number of sources of reintroduction of buckthorn

If there is a future need to install signage regarding the renaturalization, the following sign could be referred to:

[https://www.dropbox.com/s/q8f69nrj77bscc9/MVHF\\_Interpretive\\_Sign\\_Design1\\_V3.pdf?dl=0](https://www.dropbox.com/s/q8f69nrj77bscc9/MVHF_Interpretive_Sign_Design1_V3.pdf?dl=0)