Planner: K. Gonyou

Appendix E – Statement of Cultural Heritage Value or Interest

Legal Description Lot 17, RCP 1028, London

Statement of Cultural Heritage Value or Interest

Description of Property

The property at 2096 Wonderland Road North is located on the east side of Wonderland Road North between Fanshawe Park Road East and Sunningdale Road East. A two-storey brick building is located near the northeast corner of the property.

Statement of Cultural Heritage Value or Interest

The residence at 2096 Wonderland Road North has local significance for design/physical value, historical/associative value, and contextual value.

The residence at 2096 Wonderland Road North has physical or design value as a rare and representative example of a mid-19th century Georgian farmhouse. The residence is a two storey structure with a low-pitched hip roof and bookend chimneys. It has a buff brick exterior with a common bond, brick voussoirs, and a stone foundation. The Georgian style of architecture is reflected in the symmetrical façade and minimal use of ornamenting and detail.

The residence at 2096 Wonderland Road North has historical and associative value because of its link with the Warner family. William Warner was the original patent holder on the property, receiving it in 1819. His son, Wesley Warner, inherited the farmstead and was a noted member of London Township for his involvement in the temperance society.

The residence at 2096 Wonderland Road North has contextual value because it is physically and historically linked to its surroundings. It remains located in its original spot on the property and historically reflects the prominent role agriculture played in London Township.

Heritage Attributes

The heritage attributes which support or contribute to the cultural heritage value or interest of the property at 2096 Wonderland Road North include:

- Georgian two storey farmhouse
- Square shaped plan
- Low pitched hip roof with bookend chimneys
- Buff brick construction
- Field stone foundation
- Brick voussoirs above windows

•

The addition at the rear of the brick building is not considered to be a heritage attribute.