

August 9, 2013

Calvin McCourt  
Director of Planning  
Pen Equity Corporation  
10 Dundas Street East, Suite 1002  
Toronto, ON  
M5B 2G9

**BY E-MAIL**

Dear Mr. McCourt:

**Project No: 60302651**


**Regarding: Goal Ventures / Pen Equity Corporation  
Brockley Area Property, City of London  
Vegetation Patch # 10102 Surface Water Outflow**

Further to your request, on August 1 2013 we conducted a site investigation to determine and confirm the presence or absence of a surface water connection from Vegetation Patch # 10102 to Dingman Creek.

As part of our investigation, we walked the entire property and vegetation patch perimeter to search for surface water connections. As with previous site investigations, the only defined surface water outlet for the vegetation patch was located on the west side of the patch and indicates periodic and/or seasonal flow from the wetland portion of the vegetation patch to the pond west of the patch. No outlet or surface water connection was found between the vegetation patch and Dingman Creek, nor was one found between the pond and Dingman Creek.

If you have any questions or concerns, please do not hesitate to contact me at 519-650-8693 (office).

**AECOM Canada Ltd.**



Gary A. Epp, M.Sc., Ph.D.  
Manager of Ecological Services  
GAE:ge